




Beacon Wind

Survey Update

July 2020



2020 Offshore Surveys Initiated

Equinor Wind US is the lease holder of the New England offshore wind Lease Area OCS-A 0520 known as Beacon Wind. As part of the site development process, geophysical and geotechnical surveys will commence in the Beacon Wind area in early August 2020. The project will be performed by MMT US Inc. using the Offshore Supply Ship, Stril Explorer, which is equipped with the innovative Surveyor Interceptor SROV:

<https://www.mmt.se/innovations/srov/>

Equinor Wind US

Equinor Wind continues planning the Beacon Wind project in BOEM lease area OCSA-0520. The area extends 20 miles south of Nantucket MA, 128,811 acres, in water depths between 37 and 62 meters (120-200ft).

Name: STRIL EXPLORER

MMSI: 259006000

Call Sign: LAZT7

https://www.marinetraffic.com/en/ais/details/ships/shipid:197181/mmsi:25906000/imo:9484845/vessel:STRIL_EXPLORER



Beacon Wind surveys are expected to be conducted through October 2020.

An offshore fisheries representative will be onboard during the geotechnical and geophysical surveys to minimize and avoid any conflicts with fishing vessels and gear.

A scout boat will also be deployed prior to survey start to monitor the survey area of gear and will inform the fisheries liaisons who will contact gear owners for coordinated efforts.



© David Weck
MarineTraffic.com

Beacon Wind 6 Main Corner Points Coordinates

Latitude	Longitude	LORAN	LORAN
40°1.263'N	70°22.212'W	14144.1	43725.8
40°55.425'N	70°22.090'W	14165.1	43685.5
40°55.477'N	70°17.817'W	14139.5	43681.1
40°38.995'N	70°38.785'W	14313.7	43586.1
40°39.595'N	70°42.207'W	14331.9	43595.3
40°44.768'N	70°43.192'W	14320.9	43632.9

Fisheries Liaison Contacts:

Sea Risk Solutions is representing Equinor Wind as Fisheries Liaison Officers and are available 24/7 to address fisheries questions and concerns of project developments.

Elizabeth Marchetti

emarc@equinor.com

emarchetti@searisksolutions.com

401-954-2902

Steve Drew

sdrew@searisksolutions.com

908-339-7439

<http://www.searisksolutions.com/>

<https://www.equinor.com/en/what-we-do/beaconwind.html>